

Connect Box status voor monteurs

- Status
- Downstream
- Upstream
- Configuratie
- **Netwerk historie**

Netwerk historie

| Tijd | Prioriteit | Omschrijving |
|------------------------|------------|--|
| 09/11/2022 10:04:23 | notice | LAN login Success;CM-MAC=18:35:d1:00:57:ab;CMTS-MAC=00:01:5c:71:a2:47;CM-QOS=1.1;CM-VER=3.0; |
| 08/11/2022 17:14:16 | critical | No Ranging Response received - T3 time-out;CM-MAC=18:35:d1:00:57:ab;CMTS-MAC=00:01:5c:71:a2:47;CM-QOS=1.1;CM-VER=3.0; |
| 31/10/2022 18:20:59 | notice | LAN login Success;CM-MAC=18:35:d1:00:57:ab;CMTS-MAC=00:01:5c:71:a2:47;CM-QOS=1.1;CM-VER=3.0; |
| 24/10/2022 03:32:22 | critical | No Ranging Response received - T3 time-out;CM-MAC=18:35:d1:00:57:ab;CMTS-MAC=00:01:5c:71:a2:47;CM-QOS=1.1;CM-VER=3.0; |
| 23/10/2022 11:52:11 | notice | LAN login Success;CM-MAC=18:35:d1:00:57:ab;CMTS-MAC=00:01:5c:71:a2:47;CM-QOS=1.1;CM-VER=3.0; |
| 20/10/2022 21:53:34 | critical | No Ranging Response received - T3 time-out;CM-MAC=18:35:d1:00:57:ab;CMTS-MAC=00:01:5c:71:a2:47;CM-QOS=1.1;CM-VER=3.0; |

| | | |
|------------------------|----------|--|
| 19/10/2022 16:21:51 | notice | LAN login Success;CM-MAC=18:35:d1:00:57:ab;CMTS-MAC=00:01:5c:71:a2:47;CM-QOS=1.1;CM-VER=3.0; |
| 18/10/2022 11:06:12 | critical | No Ranging Response received - T3 time-out;CM-MAC=18:35:d1:00:57:ab;CMTS-MAC=00:01:5c:71:a2:47;CM-QOS=1.1;CM-VER=3.0; |
| 18/10/2022 09:40:1 | notice | LAN login Success;CM-MAC=18:35:d1:00:57:ab;CMTS-MAC=00:01:5c:71:a2:47;CM-QOS=1.1;CM-VER=3.0; |
| 11/10/2022 20:31:25 | critical | No Ranging Response received - T3 time-out;CM-MAC=18:35:d1:00:57:ab;CMTS-MAC=00:01:5c:71:a2:47;CM-QOS=1.1;CM-VER=3.0; |
| 11/10/2022 18:28:23 | notice | LAN login Success;CM-MAC=18:35:d1:00:57:ab;CMTS-MAC=00:01:5c:71:a2:47;CM-QOS=1.1;CM-VER=3.0; |
| 11/10/2022 09:42:47 | notice | SW download Successful - Via NMS |
| 11/10/2022 09:40:12 | notice | SW Download INIT - Via NMS |
| 01/01/1970 00:01:36 | critical | No Ranging Response received - T3 time-out;CM-MAC=18:35:d1:00:57:ab;CMTS-MAC=00:01:5c:71:a2:47;CM-QOS=1.1;CM-VER=3.0; |
| 21/07/2022 23:47:49 | notice | Unit has been restored to factory defaults from a software issued command;CM-MAC=18:35:d1:00:57:ab;CMTS-MAC=00:01:5c:a5:e2:46;CM-QOS=1.1;CM-VER=3.0; |
| 21/07/2022 23:46:32 | notice | LAN login Success;CM-MAC=18:35:d1:00:57:ab;CMTS-MAC=00:01:5c:a5:e2:46;CM-QOS=1.1;CM-VER=3.0; |

| | | |
|------------------------|----------|--|
| 31/01/2022 14:13:3 | Fout | DHCP RENEW sent - No response for IPv4;CM-MAC=18:35:d1:00:57:ab;CMTS-MAC=00:01:5c:a5:e2:46;CM-QOS=1.1;CM-VER=3.0; |
| 31/01/2022 14:06:41 | critical | Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=18:35:d1:00:57:ab;CMTS-MAC=00:01:5c:a5:e2:46;CM-QOS=1.1;CM-VER=3.0; |
| 31/01/2022 14:03:45 | notice | Unit has been restored to factory defaults from a software issued command;CM-MAC=18:35:d1:00:57:ab;CMTS-MAC=00:01:5c:a5:e2:46;CM-QOS=1.1;CM-VER=3.0; |
| 31/01/2022 14:03:16 | notice | LAN login Success;CM-MAC=18:35:d1:00:57:ab;CMTS-MAC=00:01:5c:a5:e2:46;CM-QOS=1.1;CM-VER=3.0; |