



CM Info

Status

Connection

Event Log

Event Log

This page displays information on the current system event log.

Time	Priority	Description
2021-09-07 14:22:26	warning	RNG-RSP CCAP Commanded Power in Excess of 6 dB Below the Value Corresponding to the Top of the DRW;CM-MAC=0c:b9:37:9a:41:fc;CMTS-MAC=00:27:90:fe:e0:ec;CM-QOS=1.1;CM-VER=3.1;
2021-09-06 20:21:45	notice	CM-STATUS message sent. Event Type Code: 6; Chan ID: 7; DSID: N/A; MAC Addr: N/A; OFDM/OFDMA Profile ID: N/A.;CM-MAC=0c:b9:37:9a:41:fc;CMTS-MAC=00:27:90:fe:e0:ec;CM-QOS=1.1;CM-VER=3.1;
2021-09-06 20:21:44	critical	Received Response to Broadcast Maintenance Request, But no Unicast Maintenance opportunities received - T4 time out;CM-MAC=0c:b9:37:9a:41:fc;CMTS-MAC=00:27:90:fe:e0:ec;CM-QOS=1.1;CM-VER=3.1;
2021-09-06 14:24:44	warning	Dynamic Range Window violation
2021-09-06 14:24:44	warning	RNG-RSP CCAP Commanded Power Exceeds Value Corresponding to the Top of the DRW;CM-MAC=0c:b9:37:9a:41:fc;CMTS-MAC=00:27:90:fe:e0:ec;CM-QOS=1.1;CM-VER=3.1;
2021-09-06 14:23:40	warning	RNG-RSP CCAP Commanded Power in Excess of 6 dB Below the Value Corresponding to the Top of the DRW;CM-MAC=0c:b9:37:9a:41:fc;CMTS-MAC=00:27:90:fe:e0:ec;CM-QOS=1.1;CM-VER=3.1;
2021-09-06 14:09:34	notice	CM-STATUS message sent. Event Type Code: 6; Chan ID: 7; DSID: N/A; MAC Addr: N/A; OFDM/OFDMA Profile ID: N/A.;CM-MAC=0c:b9:37:9a:41:fc;CMTS-MAC=00:27:90:fe:e0:ec;CM-QOS=1.1;CM-VER=3.1;
2021-09-06 14:09:33	critical	Received Response to Broadcast Maintenance Request, But no Unicast Maintenance opportunities received - T4 time out;CM-MAC=0c:b9:37:9a:41:fc;CMTS-MAC=00:27:90:fe:e0:ec;CM-QOS=1.1;CM-VER=3.1;
2021-09-06 06:48:28	notice	US profile assignment change. US Chan ID: 8; Previous Profile: 13; New Profile: 12 13.;CM-MAC=0c:b9:37:9a:41:fc;CMTS-MAC=00:27:90:fe:e0:ec;CM-QOS=1.1;CM-VER=3.1;
2021-09-06 06:38:26	notice	US profile assignment change. US Chan ID: 8; Previous Profile: 12 13; New Profile: 13.;CM-MAC=0c:b9:37:9a:41:fc;CMTS-MAC=00:27:90:fe:e0:ec;CM-QOS=1.1;CM-VER=3.1;
2021-09-06 06:05:29	warning	Dynamic Range Window violation
2021-09-06 06:05:29	warning	RNG-RSP CCAP Commanded Power Exceeds Value Corresponding to the Top of the DRW;CM-MAC=0c:b9:37:9a:41:fc;CMTS-MAC=00:27:90:fe:e0:ec;CM-QOS=1.1;CM-VER=3.1;
2021-09-06 05:57:01	warning	RNG-RSP CCAP Commanded Power in Excess of 6 dB Below the Value Corresponding to the Top of the DRW;CM-MAC=0c:b9:37:9a:41:fc;CMTS-MAC=00:27:90:fe:e0:ec;CM-QOS=1.1;CM-VER=3.1;
2021-09-06 05:53:34	warning	Dynamic Range Window violation
2021-09-06 05:53:34	warning	RNG-RSP CCAP Commanded Power Exceeds Value Corresponding to the Top of the DRW;CM-MAC=0c:b9:37:9a:41:fc;CMTS-MAC=00:27:90:fe:e0:ec;CM-QOS=1.1;CM-VER=3.1;
2021-09-06 05:53:34	warning	Dynamic Range Window violation
2021-09-06 05:53:34	warning	RNG-RSP CCAP Commanded Power Exceeds Value Corresponding to the Top of the DRW;CM-MAC=0c:b9:37:9a:41:fc;CMTS-MAC=00:27:90:fe:e0:ec;CM-QOS=1.1;CM-VER=3.1;
2021-09-06 05:53:34	warning	Dynamic Range Window violation
2021-09-06 05:53:34	warning	RNG-RSP CCAP Commanded Power Exceeds Value Corresponding to the Top of the DRW;CM-MAC=0c:b9:37:9a:41:fc;CMTS-MAC=00:27:90:fe:e0:ec;CM-QOS=1.1;CM-VER=3.1;
Time	Priority	Description

2021-09-06 05:53:34	warning	Dynamic Range Window violation
2021-09-06 05:53:34	warning	RNG-RSP CCAP Commanded Power Exceeds Value Corresponding to the Top of the DRW;CM-MAC=0c:b9:37:9a:41:fc;CMTS-MAC=00:27:90:fe:e0:ec;CM-QOS=1.1;CM-VER=3.1;
2021-09-06 05:51:11	warning	Dynamic Range Window violation
2021-09-06 05:51:11	warning	RNG-RSP CCAP Commanded Power Exceeds Value Corresponding to the Top of the DRW;CM-MAC=0c:b9:37:9a:41:fc;CMTS-MAC=00:27:90:fe:e0:ec;CM-QOS=1.1;CM-VER=3.1;
2021-09-06 05:28:58	warning	RNG-RSP CCAP Commanded Power in Excess of 6 dB Below the Value Corresponding to the Top of the DRW;CM-MAC=0c:b9:37:9a:41:fc;CMTS-MAC=00:27:90:fe:e0:ec;CM-QOS=1.1;CM-VER=3.1;
2021-09-06 03:22:46	warning	Dynamic Range Window violation
2021-09-06 03:22:46	warning	RNG-RSP CCAP Commanded Power Exceeds Value Corresponding to the Top of the DRW;CM-MAC=0c:b9:37:9a:41:fc;CMTS-MAC=00:27:90:fe:e0:ec;CM-QOS=1.1;CM-VER=3.1;
2021-09-05 20:40:06	notice	CM-STATUS message sent. Event Type Code: 8; Chan ID: 7; DSID: N/A; MAC Addr: N/A; OFDM/OFDMA Profile ID: N/A.;CM-MAC=0c:b9:37:9a:41:fc;CMTS-MAC=00:27:90:fe:e0:ec;CM-QOS=1.1;CM-VER=3.1;
2021-09-05 20:40:04	notice	CM-STATUS message sent. Event Type Code: 7; Chan ID: 7; DSID: N/A; MAC Addr: N/A; OFDM/OFDMA Profile ID: N/A.;CM-MAC=0c:b9:37:9a:41:fc;CMTS-MAC=00:27:90:fe:e0:ec;CM-QOS=1.1;CM-VER=3.1;
2021-09-05 20:40:04	critical	16 consecutive T3 timeouts while trying to range on upstream channel 8;CM-MAC=0c:b9:37:9a:41:fc;CMTS-MAC=00:27:90:fe:e0:ec;CM-QOS=1.1;CM-VER=3.1;
2021-09-05 20:40:04	critical	Ranging Request Retries exhausted;CM-MAC=0c:b9:37:9a:41:fc;CMTS-MAC=00:27:90:fe:e0:ec;CM-QOS=1.1;CM-VER=3.1;
2021-09-05 20:39:30	critical	No Ranging Response received - T3 time-out;CM-MAC=0c:b9:37:9a:41:fc;CMTS-MAC=00:27:90:fe:e0:ec;CM-QOS=1.1;CM-VER=3.1;
2021-09-05 20:39:29	notice	CM-STATUS message sent. Event Type Code: 6; Chan ID: 7; DSID: N/A; MAC Addr: N/A; OFDM/OFDMA Profile ID: N/A.;CM-MAC=0c:b9:37:9a:41:fc;CMTS-MAC=00:27:90:fe:e0:ec;CM-QOS=1.1;CM-VER=3.1;

©2021 Ubee Interactive . All rights reserved.