

3.0 Downstreamkanalen

Kanaal	Frequentie (Hz)	Vermogen (dBmV)	SNR (dB)	Modulatie	Vergrendelde status	RxMER (dB)	Gecorrigeerd (actief profiel)	Niet-gecorrigeerd (actief profiel)
1	6020000	6.8	38	QAM256	Locked	38	0	19973962
2	6100000	7.5	38	QAM256	Locked	38	5	17284397
3	6180000	7.1	38	QAM256	Locked	38	6	17248229
4	6260000	6.5	38	QAM256	Locked	38	0	17283168
5	6340000	7.2	38	QAM256	Locked	38	0	17284393
6	6420000	6.1	38	QAM256	Locked	38	2	17282185
7	6500000	7.0	38	QAM256	Locked	38	5	17285112
8	6580000	7.4	38	QAM256	Locked	38	0	17270335
9	6660000	6.5	38	QAM256	Locked	38	0	17297103
10	6740000	8.3	38	QAM256	Locked	38	0	17299635
11	6820000	8.0	38	QAM256	Locked	38	4	17298801
12	6900000	7.2	38	QAM256	Locked	38	0	17297911
13	6980000	8.1	38	QAM256	Locked	38	6	17298931
14	7060000	6.9	37	QAM256	Locked	37	0	17299487

15	714000 000	7.3	37	QAM25 6	Locked	37	4	17299799
16	722000 000	7.2	37	QAM25 6	Locked	37	5	17282933
17	730000 000	6.8	37	QAM25 6	Locked	37	0	17300727
18	738000 000	7.8	38	QAM25 6	Locked	38	0	17299819
19	746000 000	6.5	37	QAM25 6	Locked	37	0	17301011
20	754000 000	7.3	37	QAM25 6	Locked	37	4	17297128
29	826000 000	6.3	37	QAM25 6	Locked	37	0	17272487
30	834000 000	6.6	37	QAM25 6	Locked	37	18	17297478
31	842000 000	6.3	37	QAM25 6	Locked	37	4	17298065
32	850000 000	5.8	37	QAM25 6	Locked	37		

3.0 Upstreamkanalen

Kanaal	Frequentie (Hz)	Vermogen (dBmV)	Symbol rate (ksps)	Modulatie	Kanaaltyp	T3-time outs	T4-time outs
13	58800000	46	5.120000	64qam	2.0	0	0
14	52000000	46	5.120000	64qam	2.0	1	0
15	45200000	45	5.120000	64qam	2.0	1	0
16	38400000	45	5.120000	64qam	2.0	0	0

Netwerklogboek

Tijd	Prioriteit	Beschrijving
15-07-2022 15:33:21	notice	TR069 unexpected exit;CM-MAC=68:02:b8:6a:c4:26;CMTS-MAC=00:01:5c:87:e2:55;CM-QOS=1.1;CM-VER=3.0;
15-07-2022 15:33:23	notice	TR069 start;CM-MAC=68:02:b8:6a:c4:26;CMTS-MAC=00:01:5c:87:e2:55;CM-QOS=1.1;CM-VER=3.0;
15-07-2022 15:33:23	notice	TR069 stop ;CM-MAC=68:02:b8:6a:c4:26;CMTS-MAC=00:01:5c:87:e2:55;CM-QOS=1.1;CM-VER=3.0;
15-07-2022 15:33:26	notice	TR069 unexpected exit;CM-MAC=68:02:b8:6a:c4:26;CMTS-MAC=00:01:5c:87:e2:55;CM-QOS=1.1;CM-VER=3.0;
15-07-2022 15:33:28	notice	TR069 start;CM-MAC=68:02:b8:6a:c4:26;CMTS-MAC=00:01:5c:87:e2:55;CM-QOS=1.1;CM-VER=3.0;
16-07-2022 09:41:54	notice	Illegal - Dropped INPUT packet: src=104.16.66.50 MAC=00:01:5C:87:E2:46;CM-MAC=68:02:b8:6a:c4:26;CMTS-MAC=00:01:5c:87:e2:55;CM-QOS=1.1;CM-VER=3.0;
16-07-2022 09:41:56	notice	TR069 stop ;CM-MAC=68:02:b8:6a:c4:26;CMTS-MAC=00:01:5c:87:e2:55;CM-QOS=1.1;CM-VER=3.0;
16-07-2022 09:41:59	notice	TR069 unexpected exit;CM-MAC=68:02:b8:6a:c4:26;CMTS-MAC=00:01:5c:87:e2:55;CM-QOS=1.1;CM-VER=3.0;
16-07-2022 09:41:59	notice	TR069 start;CM-MAC=68:02:b8:6a:c4:26;CMTS-MAC=00:01:5c:87:e2:55;CM-QOS=1.1;CM-VER=3.0;

16-07-2 022 10:24:1 0	notice	Illegal - Dropped INPUT packet: src=35.186.194.101 MAC=00:01:5C:87:E2:46;CM-MAC=68:02:b8:6a:c4:26;CMTS-MAC =00:01:5c:87:e2:55;CM-QOS=1.1;CM-VER=3.0;
01-01-1 970 01:01:2 3	notice	Cable Modem Reboot - due to TR069 trigger reboot;CM-MAC=68:02:b8:6a:c4:26;CMTS-MAC=00:00:00:00:00:00 ;CM-QOS=1.1;CM-VER=3.0;
16-07-2 022 10:30:0 1	warning	MIMO Event MIMO: Stored MIMO=-1 post cfg file MIMO=-1;CM-MAC=68:02:b8:6a:c4:26;CMTS-MAC=00:01:5c:87:e2 :55;CM-QOS=1.1;CM-VER=3.0;
16-07-2 022 10:30:1 5	notice	Illegal - Dropped FORWARD packet: src=192.168.178.74 MAC=00:62:6E:67:01:2C;CM-MAC=68:02:b8:6a:c4:26;CMTS-MAC =00:01:5c:87:e2:55;CM-QOS=1.1;CM-VER=3.0;
16-07-2 022 10:30:1 6	critical	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=68:02:b8:6a:c4:26;CMTS-MAC=00:01:5c:87:e2:5 5;CM-QOS=1.1;CM-VER=3.0;
16-07-2 022 10:30:1 6	critical	No Ranging Response received - T3 time-out;CM-MAC=68:02:b8:6a:c4:26;CMTS-MAC=00:01:5c:87:e2:5 5;CM-QOS=1.1;CM-VER=3.0;
16-07-2 022 10:30:2 0	notice	Illegal - Dropped FORWARD packet: src=192.168.178.74 MAC=00:62:6E:67:01:2C;CM-MAC=68:02:b8:6a:c4:26;CMTS-MAC =00:01:5c:87:e2:55;CM-QOS=1.1;CM-VER=3.0;
16-07-2 022 10:30:3 4	notice	REGISTRATION COMPLETE - Waiting for Operational status;CM-MAC=68:02:b8:6a:c4:26;CMTS-MAC=00:01:5c:87:e2:55; CM-QOS=1.1;CM-VER=3.0;
16-07-2 022 10:31:2 5	notice	Illegal - Dropped INPUT packet: src=142.251.39.100 MAC=00:01:5C:87:E2:46;CM-MAC=68:02:b8:6a:c4:26;CMTS-MAC =00:01:5c:87:e2:55;CM-QOS=1.1;CM-VER=3.0;
16-07-2 022 10:31:5 9	notice	TR069 start;CM-MAC=68:02:b8:6a:c4:26;CMTS-MAC=00:01:5c:87:e2:55;C M-QOS=1.1;CM-VER=3.0;

16-07-2 notice Illegal - Dropped FORWARD packet:
022 src=2a03:2880:f273:00c7:face:b00c:0000:7260
10:37:5 MAC=01:5C:87:E2:46:86;CM-MAC=68:02:b8:6a:c4:26;CMTS-MAC
6 =00:01:5c:87:e2:55;CM-QOS=1.1;CM-VER=3.0;