

17-10-2022 20:07:02 notice GUI Login Status - Login Sucess from LAN interface; client ip=[192.168.178.12];CM-MAC=90:5c:44:6b:d7:9e;CMTS-MAC=28:52:61:fb:88:f7;CM-QOS=1.1;CM-VER=3.0;

17-10-2022 20:06:43 notice Illegal - Dropped INPUT packet: SRC=3.234.175.9 MAC=28:52:61:FB:88:19;CM-MAC=90:5c:44:6b:d7:9e;CMTS-MAC=28:52:61:fb:88:f7;CM-QOS=1.1;CM-VER=3.0;

17-10-2022 19:41:57 notice Illegal - Dropped FORWARD packet: SRC=2a03:2880:f273:00c7:face:b00c:0000:7260 MAC=52:61:FB:88:19:86;CM-MAC=90:5c:44:6b:d7:9e;CMTS-MAC=28:52:61:fb:88:f7;CM-QOS=1.1;CM-VER=3.0;

17-10-2022 19:39:16 notice GUI Login Status - Login Sucess from LAN interface; client ip=[192.168.178.12];CM-MAC=90:5c:44:6b:d7:9e;CMTS-MAC=28:52:61:fb:88:f7;CM-QOS=1.1;CM-VER=3.0;

17-10-2022 19:38:36 critical No Ranging Response received - T3 time-out;CM-MAC=90:5c:44:6b:d7:9e;CMTS-MAC=28:52:61:fb:88:f7;CM-QOS=1.1;CM-VER=3.0;

17-10-2022 19:37:52 notice Illegal - Dropped FORWARD packet: SRC=2a03:2880:f273:00c7:face:b00c:0000:7260 MAC=52:61:FB:88:19:86;CM-MAC=90:5c:44:6b:d7:9e;CMTS-MAC=28:52:61:fb:88:f7;CM-QOS=1.1;CM-VER=3.0;

17-10-2022 19:31:40 critical No Ranging Response received - T3 time-out;CM-MAC=90:5c:44:6b:d7:9e;CMTS-MAC=28:52:61:fb:88:f7;CM-QOS=1.1;CM-VER=3.0;

17-10-2022 19:30:42 notice Illegal - Dropped FORWARD packet: SRC=2a00:1450:4025:0401:0000:0000:0000:00bc MAC=52:61:FB:88:19:86;CM-MAC=90:5c:44:6b:d7:9e;CMTS-MAC=28:52:61:fb:88:f7;CM-QOS=1.1;CM-VER=3.0;

17-10-2022 19:04:04 critical No Ranging Response received - T3 time-out;CM-MAC=90:5c:44:6b:d7:9e;CMTS-MAC=28:52:61:fb:88:f7;CM-QOS=1.1;CM-VER=3.0;

17-10-2022 19:03:21 notice Illegal - Dropped FORWARD packet: SRC=2a00:1450:400e:080f:0000:0000:0000:200e MAC=52:61:FB:88:19:86;CM-MAC=90:5c:44:6b:d7:9e;CMTS-MAC=28:52:61:fb:88:f7;CM-QOS=1.1;CM-VER=3.0;

17-10-2022 18:59:44 critical No Ranging Response received - T3 time-out;CM-MAC=90:5c:44:6b:d7:9e;CMTS-MAC=28:52:61:fb:88:f7;CM-QOS=1.1;CM-VER=3.0;

17-10-2022 18:59:27 notice Illegal - Dropped FORWARD packet: SRC=2600:1901:0001:0e52:0000:0000:0000:0000 MAC=52:61:FB:88:19:86;CM-MAC=90:5c:44:6b:d7:9e;CMTS-MAC=28:52:61:fb:88:f7;CM-QOS=1.1;CM-VER=3.0;

17-10-2022 18:58:25 critical No Ranging Response received - T3 time-out;CM-MAC=90:5c:44:6b:d7:9e;CMTS-MAC=28:52:61:fb:88:f7;CM-QOS=1.1;CM-VER=3.0;

17-10-2022 18:56:32 notice Illegal - Dropped FORWARD packet: SRC=2a00:1450:400e:0803:0000:0000:2004 MAC=52:61:FB:88:19:86;CM-MAC=90:5c:44:6b:d7:9e;CMTS-MAC=28:52:61:fb:88:f7;CM-QOS=1.1;CM-VER=3.0;

17-10-2022 18:52:05 critical No Ranging Response received - T3 time-out;CM-MAC=90:5c:44:6b:d7:9e;CMTS-MAC=28:52:61:fb:88:f7;CM-QOS=1.1;CM-VER=3.0;

17-10-2022 18:49:21 notice Illegal - Dropped FORWARD packet: SRC=2a00:1450:4025:0401:0000:0000:0000:00bc MAC=52:61:FB:88:19:86;CM-MAC=90:5c:44:6b:d7:9e;CMTS-MAC=28:52:61:fb:88:f7;CM-QOS=1.1;CM-VER=3.0;

17-10-2022 15:37:40 critical No Ranging Response received - T3 time-out;CM-MAC=90:5c:44:6b:d7:9e;CMTS-MAC=28:52:61:fb:88:f7;CM-QOS=1.1;CM-VER=3.0;

17-10-2022 15:36:52 notice Illegal - Dropped INPUT packet: SRC=216.58.214.10 MAC=28:52:61:FB:88:19;CM-MAC=90:5c:44:6b:d7:9e;CMTS-MAC=28:52:61:fb:88:f7;CM-QOS=1.1;CM-VER=3.0;

17-10-2022 13:39:02 critical No Ranging Response received - T3 time-out;CM-MAC=90:5c:44:6b:d7:9e;CMTS-MAC=28:52:61:fb:88:f7;CM-QOS=1.1;CM-VER=3.0;

17-10-2022 13:39:01 notice Illegal - Dropped FORWARD packet: SRC=2a03:2880:f045:0012:face:b00c:0000:0002 MAC=52:61:FB:88:19:86;CM-MAC=90:5c:44:6b:d7:9e;CMTS-MAC=28:52:61:fb:88:f7;CM-QOS=1.1;CM-VER=3.0;

16-10-2022 15:04:44 critical No Ranging Response received - T3 time-out;CM-MAC=90:5c:44:6b:d7:9e;CMTS-MAC=28:52:61:fb:88:f7;CM-QOS=1.1;CM-VER=3.0;

16-10-2022 15:04:44 notice Illegal - Dropped INPUT packet: SRC=54.72.231.100 MAC=28:52:61:FB:88:19;CM-MAC=90:5c:44:6b:d7:9e;CMTS-MAC=28:52:61:fb:88:f7;CM-QOS=1.1;CM-VER=3.0;

15-10-2022 17:45:19 warning [90:5C:44:7C:67:BA][DFS] Radar signal detected, DFS sequence applied, channel changed from 56 to 44