

Na vervangen kabel (AOP -> Modem)

Network Log

Time	Priority	Description
14-05-2021 13:18:04	notice	GUI Login Status - Login Success from LAN interface; client ip=[192.168.178.109];CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
14-05-2021 12:47:29	warning	[54:67:51:E2:0E:D8][DFS] Radar signal detected, DFS sequence applied, channel changed from 56 to 40
14-05-2021 12:46:31	notice	Illegal - Dropped FORWARD packet: SRC=2001:0730:3e08:0050:0084:0116:0045:0119 MAC=01:5C:AF:00:46:86;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
14-05-2021 12:42:00	notice	TR069 start;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
14-05-2021 12:41:57	notice	Illegal - Dropped FORWARD packet: SRC=192.168.178.108 MAC=54:60:09:F7:E8:9E;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
14-05-2021 12:41:08	notice	REGISTRATION COMPLETE - Waiting for Operational status;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
14-05-2021 12:40:50	notice	Illegal - Dropped FORWARD packet: SRC=192.168.178.108 MAC=54:60:09:F7:E8:9E;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
14-05-2021 12:40:46	notice	TLV-11 - unrecognized OID;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
14-05-2021 12:40:32	warning	MIMO Event MIMO: Stored MIMO=-1 post cfg file MIMO=-1;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;

01-01-1970 00:01:39	critical	No Ranging Response received - T3 time-out;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
01-01-1970 00:01:18	notice	Cable Modem Reboot - due to power reset;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.1;CM-VER=3.0;
14-05-2021 12:36:35	notice	GUI Token verify failed; client ip=[192.168.178.109];CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
14-05-2021 12:34:16	notice	Illegal - Dropped FORWARD packet: SRC=2603:1026:0206:0001:0000:0000:0000:0002 MAC=01:5C:AF:00:46:86;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
14-05-2021 12:30:54	notice	GUI Login Status - Login Success from LAN interface; client ip=[192.168.178.143];CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
14-05-2021 11:58:52	notice	Illegal - Dropped FORWARD packet: SRC=2a04:4e42:0009:0000:0000:0000:0000:0760 MAC=01:5C:AF:00:46:86;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
14-05-2021 01:01:35	critical	No Ranging Response received - T3 time-out;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
13-05-2021 22:58:17	notice	Illegal - Dropped FORWARD packet: SRC=2a00:1450:400e:0022:0000:0000:0000:000b MAC=01:5C:AF:00:46:86;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
13-05-2021 21:21:38	notice	GUI Login Status - Login Success from LAN interface; client ip=[192.168.178.66];CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
13-05-2021 20:58:58	notice	Illegal - Dropped FORWARD packet: SRC=2a01:0578:0003:0000:0000:0000:22f6:70cf MAC=01:5C:AF:00:46:86;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;

13-05-2021 01:14:01	critical	No Ranging Response received - T3 time-out;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
12-05-2021 23:28:57	notice	Illegal - Dropped FORWARD packet: SRC=2001:09a8:0000:000e:1337:0000:0080:0002 MAC=01:5C:AF:00:46:86;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;

[Refresh data](#)

Downstream bonded channels

Channel	Frequency (Hz)	Power (dBmV)	SNR (dB)	Modulation	Channel ID
1	602000000	7	38	256qam	1
2	610000000	6	37	256qam	2
3	618000000	6	37	256qam	3
4	626000000	7	37	256qam	4
5	634000000	7	37	256qam	5
6	642000000	7	38	256qam	6
7	650000000	7	37	256qam	7
8	658000000	7	37	256qam	8
9	666000000	7	37	256qam	9
10	674000000	7	37	256qam	10
11	682000000	7	38	256qam	11

12	690000000	7	38	256qam	12
13	698000000	7	38	256qam	13
14	714000000	6	37	256qam	15
15	746000000	6	37	256qam	19
16	754000000	6	37	256qam	20
17	762000000	6	37	256qam	21
18	770000000	5	37	256qam	22
19	778000000	5	37	256qam	23
20	786000000	5	37	256qam	24
21	826000000	4	37	256qam	29
22	834000000	3	37	256qam	30
23	842000000	3	37	256qam	31
24	850000000	3	37	256qam	32

Downstream bonded channels

Channel	Locked Status	RxMER (dB)	Pre RS Errors	Post RS Errors
1	Locked	38.605	83487890	13
2	Locked	37.636	80693251	17
3	Locked	37.636	80695782	19

4	Locked	37.636	80696943	6
5	Locked	37.356	80697462	5
6	Locked	38.605	80693194	4
7	Locked	37.636	80697822	5
8	Locked	37.636	80698330	5
9	Locked	37.636	80693418	6
10	Locked	37.636	80698690	4
11	Locked	38.605	80700265	6
12	Locked	38.605	80700770	5
13	Locked	38.605	80701843	4
14	Locked	37.636	80689883	6
15	Locked	37.356	80702363	5
16	Locked	37.636	80690261	7
17	Locked	37.636	80704343	1
18	Locked	37.356	80705712	5
19	Locked	37.356	80708213	6
20	Locked	37.636	80691651	21
21	Locked	37.356	80690705	5
22	Locked	37.356	80711058	0

23	Locked	37.356	80709861	8
24	Locked	37.356	80711693	9

Upstream bonded channels

Channel	Frequency (Hz)	Power (dBmV)	Symbol Rate (ksps)	Modulation	Channel ID
1	57800000	42	5.120	64qam	7
2	28600000	43	2.560	64qam	12
3	31800000	42	2.560	64qam	11
4	37100000	42	5.120	64qam	10
5	44000000	42	5.120	64qam	9
6	50900000	42	5.120	64qam	8

Upstream bonded channels

Channel	Channel Type	T1 Timeouts	T2 Timeouts	T3 Timeouts	T4 Timeouts
1	2.0	0	0	1	0
2	2.0	0	0	0	0
3	2.0	0	0	0	0
4	2.0	0	0	0	0

5	2.0	0	0	0	0
6	2.0	0	0	0	0