


## Rechstreeks kabeltje in AOP zonder splitter



## ownstream bonded channels

Channel	Frequency (Hz)	Power (dBmV)	SNR (dB)	Modulation	Channel ID
1	626000000	7	37	256qam	4
2	602000000	7	38	256qam	1
3	618000000	7	37	256qam	3
4	634000000	7	37	256qam	5
5	642000000	7	38	256qam	6
6	650000000	7	37	256qam	7
7	658000000	7	37	256qam	8
8	666000000	7	37	256qam	9

9	67400000 0	7	37	256qam	10
10	68200000 0	7	37	256qam	11
11	69000000 0	7	38	256qam	12
12	69800000 0	7	37	256qam	13
13	70600000 0	7	37	256qam	14
14	71400000 0	7	37	256qam	15
15	72200000 0	7	37	256qam	16
16	73000000 0	7	38	256qam	17
17	73800000 0	7	37	256qam	18
18	74600000 0	7	37	256qam	19
19	75400000 0	6	37	256qam	20
20	77000000 0	6	37	256qam	22
21	82600000 0	4	37	256qam	29
22	83400000 0	3	37	256qam	30

23	84200000 0	3	37	256qam	31
24	85000000 0	3	37	256qam	32

### Downstream bonded channels

Channel	Locked Status	RxMER (dB)	Pre RS Errors	Post RS Errors
1	Locked	37.636	108871615	19
2	Locked	38.605	106129000	12
3	Locked	37.636	106139048	5
4	Locked	37.636	106139025	5
5	Locked	38.605	106136953	4
6	Locked	37.636	106135558	6
7	Locked	37.356	106123149	7
8	Locked	37.636	106120752	5
9	Locked	37.636	106122943	5
10	Locked	37.636	106135415	7
11	Locked	38.605	106138681	6
12	Locked	37.636	106137866	6
13	Locked	37.636	106140731	5
14	Locked	37.356	106143218	6

15	Locked	37.636	106119955	5
16	Locked	38.605	106135036	8
17	Locked	37.636	106135961	6
18	Locked	37.636	106141564	6
19	Locked	37.636	106143486	6
20	Locked	37.636	106143995	4
21	Locked	37.356	106117709	7
22	Locked	37.356	106143845	8
23	Locked	37.356	106138963	6
24	Locked	37.636	106139608	12

#### Upstream bonded channels

Channel	Frequency (Hz)	Power (dBmV)	Symbol Rate (ksps)	Modulation	Channel ID
1	57800000	42	5.120	64qam	7
2	28600000	42	2.560	64qam	12
3	31800000	42	2.560	64qam	11
4	37100000	42	5.120	64qam	10
5	44000000	42	5.120	64qam	9
6	50900000	42	5.120	64qam	8

## Upstream bonded channels

Channel	Channel Type	T1 Timeouts	T2 Timeouts	T3 Timeouts	T4 Timeouts
1	2.0	0	0	0	0
2	2.0	0	0	0	0
3	2.0	0	0	0	0
4	2.0	0	0	0	0
5	2.0	0	0	0	0
6	2.0	0	0	0	0
Time	Priority	Description			
17-05-2021 15:23:47	notice	GUI Login Status - Login Sucess from LAN interface; client ip=[192.168.178.109];CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;			
17-05-2021 14:49:51	notice	Illegal - Dropped FORWARD packet: SRC=2a00:0d00:0003:0007:0000:0000:0000:0068 MAC=01:5C:AF:00:46:86;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;			
17-05-2021 14:35:44	warning	[54:67:51:E2:0E:D8][DFS] Radar signal detected, DFS sequence applied, channel changed from 116 to 44			
17-05-2021 14:34:41	notice	GUI Login Status - Login Sucess from LAN interface; client ip=[192.168.178.109];CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;			
17-05-2021 14:34:36	notice	Illegal - Dropped FORWARD packet: SRC=2a00:1450:4025:0401:0000:0000:0000:00bc MAC=01:5C:AF:00:46:86;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;			

17-05-2021 14:33:15	notice	TR069 start;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
17-05-2021 14:33:12	notice	Illegal - Dropped FORWARD packet: SRC=192.168.178.185 MAC=92:32:2D:A6:62:A5;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
17-05-2021 14:32:24	notice	REGISTRATION COMPLETE - Waiting for Operational status;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
17-05-2021 14:32:05	notice	Illegal - Dropped FORWARD packet: SRC=192.168.178.66 MAC=0A:E9:62:BB:AD:BF;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
17-05-2021 14:32:01	notice	TLV-11 - unrecognized OID;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
17-05-2021 14:31:49	warning	MIMO Event MIMO: Stored MIMO=-1 post cfg file MIMO=-1;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
01-01-1970 00:01:18	notice	Cable Modem Reboot - due to power reset;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.1;CM-VER=3.0;
17-05-2021 14:12:04	notice	Illegal - Dropped FORWARD packet: SRC=2a00:1450:400e:0803:0000:0000:0000:2004 MAC=01:5C:AF:00:46:86;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
17-05-2021 13:26:24	notice	GUI Login Status - Login Success from LAN interface; client ip=[192.168.178.109];CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
17-05-2021 13:25:26	notice	Illegal - Dropped FORWARD packet: SRC=2606:2800:0133:206e:1315:22a5:2006:24fd MAC=01:5C:AF:00:46:86;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;

17-05-2021 12:58:43	notice	GUI Login Status - Login Success from LAN interface; client ip=[192.168.178.109];CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
17-05-2021 12:56:24	notice	Illegal - Dropped FORWARD packet: SRC=2620:01ec:000c:0000:0000:0000:0011 MAC=01:5C:AF:00:46:86;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
17-05-2021 12:51:58	notice	TR069 start;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
17-05-2021 12:51:54	notice	Illegal - Dropped FORWARD packet: SRC=192.168.178.108 MAC=54:60:09:F7:E8:9E;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
17-05-2021 12:51:11	notice	REGISTRATION COMPLETE - Waiting for Operational status;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
17-05-2021 12:50:57	critical	No Ranging Response received - T3 time-out;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;