

Na een middag/avond + nacht draaien in de nieuwe situatie

Downstream bonded channels

Channel	Frequency (Hz)	Power (dBmV)	SNR (dB)	Modulation	Channel ID
1	626000000	7	37	256qam	4
2	602000000	7	38	256qam	1
3	618000000	7	37	256qam	3
4	634000000	8	37	256qam	5
5	642000000	8	38	256qam	6
6	650000000	7	37	256qam	7
7	658000000	7	37	256qam	8
8	666000000	7	37	256qam	9
9	674000000	8	37	256qam	10
10	682000000	8	37	256qam	11
11	690000000	8	38	256qam	12
12	698000000	7	37	256qam	13

13	70600000 0	7	37	256qam	14
14	71400000 0	7	37	256qam	15
15	72200000 0	7	37	256qam	16
16	73000000 0	7	38	256qam	17
17	73800000 0	7	37	256qam	18
18	74600000 0	7	37	256qam	19
19	75400000 0	7	37	256qam	20
20	77000000 0	6	37	256qam	22
21	82600000 0	4	37	256qam	29
22	83400000 0	4	37	256qam	30
23	84200000 0	4	37	256qam	31
24	85000000 0	4	37	256qam	32

Downstream bonded channels

Channel	Locked Status	RxMER (dB)	Pre RS Errors	Post RS Errors
---------	---------------	------------	---------------	----------------

1	Locked	37.636	2260018484	28
2	Locked	38.605	2257276018	19
3	Locked	37.356	2257286084	19
4	Locked	37.636	2257286107	12
5	Locked	38.605	2257286790	8
6	Locked	37.636	2257287225	25
7	Locked	37.356	2257275018	10
8	Locked	37.636	2257272608	13
9	Locked	37.636	2257274835	6
10	Locked	37.636	2257287267	11
11	Locked	38.605	2257290515	13
12	Locked	37.636	2257289649	21
13	Locked	37.636	2257292562	10
14	Locked	37.636	2257294971	10
15	Locked	37.636	2257272071	21
16	Locked	38.605	2257287069	30
17	Locked	37.636	2257288071	9
18	Locked	37.636	2257293618	28
19	Locked	37.636	2257295557	10

20	Locked	37.356	2257296044	22
21	Locked	37.356	2257270232	31
22	Locked	37.356	2257296359	57
23	Locked	37.356	2257291750	57
24	Locked	37.356	2257293979	49

[Refresh data](#)

Upstream bonded channels

Channel	Frequency (Hz)	Power (dBmV)	Symbol Rate (ksps)	Modulation	Channel ID
1	57800000	42	5.120	64qam	7
2	28600000	42	2.560	64qam	12
3	31800000	42	2.560	64qam	11
4	37100000	42	5.120	64qam	10
5	44000000	42	5.120	64qam	9
6	50900000	42	5.120	64qam	8

Upstream bonded channels

Channel	Channel Type	T1 Timeouts	T2 Timeouts	T3 Timeouts	T4 Timeouts
1	2.0	0	0	0	0

2	2.0	0	0	0	0
3	2.0	0	0	0	0
4	2.0	0	0	0	0
5	2.0	0	0	0	0
6	2.0	0	0	0	0

Network Log

Time	Priority	Description
18-05-2021 08:55:03	notice	GUI Login Status - Login Sucess from LAN interface; client ip=[192.168.178.143];CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
18-05-2021 08:53:42	notice	Illegal - Dropped FORWARD packet: SRC=2a03:2880:f206:00c6:face:b00c:0000:7260 MAC=01:5C:AF:00:46:86;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
17-05-2021 15:23:47	notice	GUI Login Status - Login Sucess from LAN interface; client ip=[192.168.178.109];CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
17-05-2021 14:49:51	notice	Illegal - Dropped FORWARD packet: SRC=2a00:0d00:0003:0007:0000:0000:0000:0068 MAC=01:5C:AF:00:46:86;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
17-05-2021 14:35:44	warning	[54:67:51:E2:0E:D8][DFS] Radar signal detected, DFS sequence applied, channel changed from 116 to 44
17-05-2021 14:34:41	notice	GUI Login Status - Login Sucess from LAN interface; client ip=[192.168.178.109];CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
17-05-2021 14:34:36	notice	Illegal - Dropped FORWARD packet: SRC=2a00:1450:4025:0401:0000:0000:0000:00bc

		MAC=01:5C:AF:00:46:86;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
17-05-2021 14:33:15	notice	TR069 start;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
17-05-2021 14:33:12	notice	Illegal - Dropped FORWARD packet: SRC=192.168.178.185 MAC=92:32:2D:A6:62:A5;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
17-05-2021 14:32:24	notice	REGISTRATION COMPLETE - Waiting for Operational status;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
17-05-2021 14:32:05	notice	Illegal - Dropped FORWARD packet: SRC=192.168.178.66 MAC=0A:E9:62:BB:AD:BF;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
17-05-2021 14:32:01	notice	TLV-11 - unrecognized OID;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
17-05-2021 14:31:49	warning	MIMO Event MIMO: Stored MIMO=-1 post cfg file MIMO=-1;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
01-01-1970 00:01:18	notice	Cable Modem Reboot - due to power reset;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.1;CM-VER=3.0;
17-05-2021 14:12:04	notice	Illegal - Dropped FORWARD packet: SRC=2a00:1450:400e:0803:0000:0000:0000:2004 MAC=01:5C:AF:00:46:86;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
17-05-2021 13:26:24	notice	GUI Login Status - Login Success from LAN interface; client ip=[192.168.178.109];CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
17-05-2021 13:25:26	notice	Illegal - Dropped FORWARD packet: SRC=2606:2800:0133:206e:1315:22a5:2006:24fd MAC=01:5C:AF:00:46:86;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;

17-05-2021 12:58:43	notice	GUI Login Status - Login Success from LAN interface; client ip=[192.168.178.109];CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
17-05-2021 12:56:24	notice	Illegal - Dropped FORWARD packet: SRC=2620:01ec:000c:0000:0000:0000:0011 MAC=01:5C:AF:00:46:86;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
17-05-2021 12:51:58	notice	TR069 start;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;
17-05-2021 12:51:54	notice	Illegal - Dropped FORWARD packet: SRC=192.168.178.108 MAC=54:60:09:F7:E8:9E;CM-MAC=54:67:51:d6:8b:c8;CMTS-MAC=00:01:5c:af:00:56;CM-QOS=1.1;CM-VER=3.0;