

## Netwerkinformatie

Status      Downstream      Upstream      Configuratie      Netwerkklogboek

### 3.0 Downstreamkanalen

Kanaal	Frequentie (Hz)	Vermogen (dBmV)	SNR (dB)	Modulatie	Vergrendelde status	RxMER (dB)
1	602000000	4.2	38	QAM256	Locked	38
2	610000000	4.6	38	QAM256	Locked	38
3	618000000	4.7	38	QAM256	Locked	38
4	626000000	4.6	38	QAM256	Locked	38
5	634000000	4.3	38	QAM256	Locked	38
6	642000000	4.3	38	QAM256	Locked	38
7	650000000	4.4	38	QAM256	Locked	38
8	658000000	4.4	38	QAM256	Locked	38
9	666000000	4.6	38	QAM256	Locked	38
10	674000000	5.1	38	QAM256	Locked	38
11	682000000	5.3	38	QAM256	Locked	38
12	690000000	5.3	38	QAM256	Locked	38
13	698000000	5.3	38	QAM256	Locked	38
14	706000000	5.5	38	QAM256	Locked	38
15	714000000	5.4	38	QAM256	Locked	38
16	722000000	5.0	38	QAM256	Locked	38

### 3.0 Upstreamkanalen

Kanaal	Frequentie (Hz)	Vermogen (dBmV)	Symbol rate (ksps)	Modulatie	Kanaaltype	T3-
1	58800000	45	5.120000	64qam	2.0	0
2	52000000	45	5.120000	64qam	2.0	1
3	45200000	45	5.120000	64qam	2.0	2
4	38400000	44	5.120000	64qam	2.0	0

Meer krijg ik niet te zien

**Netwerklogboek**

Tijd	Prioriteit	Beschrijving
13-07-2022 18:15:05	critical	No Ranging Response received - T3 time-out;CM-MAC=68:02:b8:7c:0c:71;CMTS-MAC=00:01:5c:96:f8:63;CM-QOS=1.1;CM-VER=3.0;
14-07-2022 03:29:15	notice	Illegal - Dropped INPUT packet: SRC=176.34.214.23 MAC=00:01:5C:96:F8:46;CM-MAC=68:02:b8:7c:0c:71;CMTS-MAC=00:01:5c:96:f8:63;CM-QOS=1.1;CM-VER=3.0;
14-07-2022 03:34:36	error	DHCP RENEW WARNING - Field invalid in response v4 option;CM-MAC=68:02:b8:7c:0c:71;CMTS-MAC=00:01:5c:96:f8:63;CM-QOS=1.1;CM-VER=3.0;
14-07-2022 09:56:19	notice	Illegal - Dropped INPUT packet: SRC=172.217.168.234 MAC=00:01:5C:96:F8:46;CM-MAC=68:02:b8:7c:0c:71;CMTS-MAC=00:01:5c:96:f8:63;CM-QOS=1.1;CM-VER=3.0;
01-01-1970 01:01:23	notice	Cable Modem Reboot - due to power reset;CM-MAC=68:02:b8:7c:0c:71;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.1;CM-VER=3.0;
14-07-2022 10:05:28	notice	Illegal - Dropped FORWARD packet: SRC=192.168.178.185 MAC=98:EE:CB:3B:A2:F1;CM-MAC=68:02:b8:7c:0c:71;CMTS-MAC=00:01:5c:96:f8:63;CM-QOS=1.1;CM-VER=3.0;
14-07-2022 10:05:28	warning	MIMO Event MIMO: Stored MIMO=-1 post cfg file MIMO=-1;CM-MAC=68:02:b8:7c:0c:71;CMTS-MAC=00:01:5c:96:f8:63;CM-QOS=1.1;CM-VER=3.0;
14-07-2022 10:05:30	notice	Illegal - Dropped FORWARD packet: SRC=192.168.178.185 MAC=98:EE:CB:3B:A2:F1;CM-MAC=68:02:b8:7c:0c:71;CMTS-MAC=00:01:5c:96:f8:63;CM-QOS=1.1;CM-VER=3.0;
14-07-2022 10:05:44	notice	REGISTRATION COMPLETE - Waiting for Operational status;CM-MAC=68:02:b8:7c:0c:71;CMTS-MAC=00:01:5c:96:f8:63;CM-QOS=1.1;CM-VER=3.0;

14-07-2022 10:07:00	notice	Illegal - Dropped INPUT packet: SRC=35.190.27.197 MAC=00:01:5C:96:F8:46;CM- MAC=68:02:b8:7c:0c:71;CMTS- MAC=00:01:5c:96:f8:63;CM-QOS=1.1;CM-VER=3.0;
14-07-2022 10:07:04	notice	TR069 start;CM-MAC=68:02:b8:7c:0c:71;CMTS- MAC=00:01:5c:96:f8:63;CM-QOS=1.1;CM-VER=3.0;
14-07-2022 11:27:46	notice	Illegal - Dropped INPUT packet: SRC=23.51.68.110 MAC=00:01:5C:96:F8:46;CM- MAC=68:02:b8:7c:0c:71;CMTS- MAC=00:01:5c:96:f8:63;CM-QOS=1.1;CM-VER=3.0;
14-07-2022 11:29:05	critical	No Ranging Response received - T3 time-out;CM- MAC=68:02:b8:7c:0c:71;CMTS- MAC=00:01:5c:96:f8:63;CM-QOS=1.1;CM-VER=3.0;
17-07-2022 04:14:03	notice	Illegal - Dropped INPUT packet: SRC=60.160.229.92 MAC=00:01:5C:96:F8:46;CM- MAC=68:02:b8:7c:0c:71;CMTS- MAC=00:01:5c:96:f8:63;CM-QOS=1.1;CM-VER=3.0;
17-07-2022 04:16:14	critical	No Ranging Response received - T3 time-out;CM- MAC=68:02:b8:7c:0c:71;CMTS- MAC=00:01:5c:96:f8:63;CM-QOS=1.1;CM-VER=3.0;
17-07-2022 05:15:32	notice	Illegal - Dropped INPUT packet: SRC=142.251.39.106 MAC=00:01:5C:96:F8:46;CM- MAC=68:02:b8:7c:0c:71;CMTS- MAC=00:01:5c:96:f8:63;CM-QOS=1.1;CM-VER=3.0;
17-07-2022 05:16:57	critical	No Ranging Response received - T3 time-out;CM- MAC=68:02:b8:7c:0c:71;CMTS- MAC=00:01:5c:96:f8:63;CM-QOS=1.1;CM-VER=3.0;
17-07-2022 15:07:06	notice	Illegal - Dropped INPUT packet: SRC=104.110.191.28 MAC=00:01:5C:96:F8:46;CM- MAC=68:02:b8:7c:0c:71;CMTS- MAC=00:01:5c:96:f8:63;CM-QOS=1.1;CM-VER=3.0;
17-07-2022 15:14:33	notice	GUI Login Status - Login Fail from LAN interface; client ip=[192.168.178.185];CM- MAC=68:02:b8:7c:0c:71;CMTS- MAC=00:01:5c:96:f8:63;CM-QOS=1.1;CM-VER=3.0;
17-07-2022 15:20:11	notice	Illegal - Dropped INPUT packet: SRC=91.218.213.49 MAC=00:01:5C:96:F8:46;CM- MAC=68:02:b8:7c:0c:71;CMTS- MAC=00:01:5c:96:f8:63;CM-QOS=1.1;CM-VER=3.0;